

PORTABLE MAGNETIC DRILLS

		HMD130	HMD2X2	HMD900	HMD904	HMD905	HMD927	HMD920	HMD918	HMD934
		Low Profile		Fabricating			Heavy Duty Drilling			
Cutters	RotaLoc Plus™	\checkmark	With Adapter	With Adapter	With Adapter	With Adapter	With Adapter	With Adapter	With Adapter	
	"12,000-Series"		\checkmark		\checkmark		\checkmark			
	Copperhead™ Carbide Tipped		\checkmark	\checkmark	\checkmark	\checkmark	\checkmark	\checkmark	\checkmark	
Model Specifications	Diameter Min./Max.	7/16" to 1-3/8" (12 - 35mm)	7/16" to 2" (12 - 50mm)	7/16" to 1-1/2" (12 - 38mm)	7/16" to 1-1/2" (12 - 38mm)	7/16" to 2" (12 - 50mm)	7/16" to 2" (12 - 50mm)	7/16" to 2-3/8" (12 - 60mm)	7/16" to 2-3/8" (12 - 60mm)	3/4" to 3-1/16" (19 - 77mm)
	Depth Max.	1" (25mm)	2" (50mm)	2" (50mm)	2" (50mm)	2" (50mm)	2" (50mm)	3" (76mm)	6" (152mm)	4" (100mm)
	Cutter Mounting	Bayonet Style	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat	3/4" Double Flat
	No-Load R.P.M.	450	300 / 450	450	450	250 / 450	250 / 450	250 / 450 / 700	250 / 450	70 / 120 200 / 332
	Model Weight	23.8 lbs (10.8 kg)	29.2 lbs (13.2 kg)	27.7 lbs (12.6 kg)	30 lbs (13.6 kg)	35 lbs (15.9 kg)	43 lbs (19.5 kg)	49 lbs (22.2 kg)	44.2 lbs (20.1 kg)	72 lbs (32.6 kg)
L	Thru-the-Tool Coolant				\checkmark	\checkmark	\checkmark	\checkmark	\checkmark	\checkmark
Available Accessories	Carrying Case Included		\checkmark							
	Swivel Base				Optional	Optional		Optional		
	#2 Morse Taper							With Adapter	With Adapter	
	Pipe Adapter			\checkmark	\checkmark	\checkmark	Manual Mode		\checkmark	
	Tap Attachment				\checkmark		Manual Mode	\checkmark		
	Vac-Pad [™]			\checkmark	\checkmark	\checkmark				
	Coolant Bottle				Optional	Included	Included	Included	Pressurized	Included
	Countersink Kit			\checkmark	\checkmark	\checkmark	Manual Mode	\checkmark	\checkmark	\checkmark
	Twist Drill Adapter						Manual Mode	\checkmark		
	Ratchet Drive	\checkmark	\checkmark		\checkmark	\checkmark		\checkmark	\checkmark	
	Arbor Extender				\checkmark		Manual Mode			
	Drill Chuck				\checkmark		Manual Mode	\checkmark	\checkmark	
	RotaLoc™ Spindle Adapter				\checkmark	\checkmark	Manual Mode	\checkmark		